

Eastlake Water Services
16720 S. Carlin Bay Rd
Harrison, ID 83833

Carlin Bay Property Owners
Water Report for February 2012

Operations

Operation of plant during month of February was well within DEQ specifications and requirements.

Alum pump was replaced with the backup LMI pump due to decrease flow rate. The low flow rate caused a plant shut down due to a high turbidity reading greater than 0.250 NTU's.

Maintenance

Rebuilt the Alum pump which involved replacing two check valves with O-rings and diaphragm. Cleaned the pumps 4-way control valve. Will order two new pump diaphragms to replace spare parts inventory.

Eastlake Electric replaced lighting fixtures in filter room and lab. Also new outside lights were installed adjacent to all outside doors.

Actions needed by CBPOA

No action required