

Eastlake Water Services
16720 S. Carlin Bay Rd
Harrison, ID 83833

Carlin Bay Property Owners
Water Report for May 2013

Operations

Plant operations have been within DEQ specifications for the month of May, there were no violations.

DEQ conducted there 5 year sanitary survey on June 11th. There were two discrepancies that need to be addressed. They are replacing a screen that covers the overflow pipe at the clear well and adding additional sealant to the reservoir steel covers. Overall they were very impressed with the operations and stated that it was one of their top three water plants.

Maintenance

I've been promised by Hometown Concrete that they will replace the sealant on reservoir 1 within the month of June and seal the clear well tank that is not covered by the building. Reservoir 1 work will be done under warranty. It will require grinding the old sealant off the lid before applying the new sealant.

R.C. Worst replaced the 1 ½" ABS pipe to the air gap drain but did not repair the leak at the 6 inch flare which is the receiving end of the air gap. I have rescheduled for them to make the repair on Tuesday, June 18th.

I have also asked R.C. Worst to add an additional gasket to the reservoir steel tank covers and replace the overflow pipe screen at the clear well.

Actions needed by CBPOA

Write a letter to water customers advising them that it is time again for a yearly inspection on their cross connection devices.