

Eastlake Water Services
16720 S. Carlin Bay Rd
Harrison, ID 83833

Carlin Bay Property Owners
Water Report for June-Aug 2013

Operations

Plant operations have been within DEQ specifications for the months of June, July and August, there were no violations.

We are having numerous failures (circuit breaker tripping) on pump 2 which pumps water from clear well to reservoir 1. This problem is getting progressively worse.

Eastlake Water Services received the cross connection survey reports from Water Wizards the last week of August. A copy of the updated cross connection spread sheet was given to Tony Verdoia on 9/3/2013.

Distribution lines were flushed in June. The lines will be flushed again this September.

The 1720E turbidity meters and the hand held turbidity meter were calibrated for this quarter of the year.

Maintenance

Reservoir 2 had a coat of maintenance sealer applied. Reservoir 1 had the sealer that was flaking ground off and a new coat of sealer was then applied to the top. This work was covered under warranty. The clear well top not covered by the water plant building was sealed with same material that was applied to reservoir 1 and 2.

Per DEQ survey requirements the following was done by Eastlake Water Services. A new pH meter was purchased and is now being used for pH tests. The screen was replaced on the overflow pipe at the clear well. A new gasket was installed on reservoir 2's man hole cover.

The 2, 4D and disinfection by product tests have been completed for this year.

Actions needed by CBPOA

Advise Homeowners of cross connection discrepancies so they can correct.

CBPOA Board approval for Eastlake Water Services to call United Pump to evaluate pump 2 at the clear well.