

Eastlake Water Services
16720 S. Carlin Bay Rd
Harrison, ID 83833

Carlin Bay Property Owners
Water Report for July 2012

Operations

Plant operation was within DEQ specifications for the month of July, there were no violations.

Maintenance

We had severe lightning storms this month that caused damage to a telemetry transceiver and a water level sensor at reservoir #2. Called Automatic Electrical Systems (AES), they could not respond for a couple of days. Called H2E about our situation. They sent a crew out who evaluated our system that day. They suspected a bad transceiver and a lightning surge suppressor but could not confirm. I swapped the lake pump transceiver with the suspected bad transceiver at reservoir 1. Communications were restored. H2E did not have a transceiver in stock. Called AES who did have one. AES came out the next day, replaced transceiver and found a bad level transducer. Replaced level sensor and surge suppressor.

Water Plant painting bids were submitted to the board for approval. T. K.'s Painting submitted a bid for \$2,800 and J.L. Painting's bid was \$1,300. Bid was to power wash building and apply two coats of stain and back brush between coats. J.L. Painting was selected by the BOD.

Actions needed by CBPOA

No actions required