

Eastlake Water Services
16720 S. Carlin Bay Rd
Harrison, ID 83833

Carlin Bay Property Owners
Water Report for June 2012

Operations

Plant operation was within DEQ specifications for the month of June, there were no violations.

Sapphire Landscaping was here the 15th and 16th of June to do cross connection surveys and testing. There was one incident of a cross connection. The water customer was notified and asked to correct the problem by Sapphire Landscaping. I will give a report on the cross connection survey once I have the survey records.

A 2,4-D test sample was taken to Accurate Labs for evaluation. Results of their tests showed 2,4-D to be non detectable in our water.

The consumer confidence report for the year 2011 was completed and sent to DEQ and Carlin Bay Property Owners board of directors for publication.

We had a suspected water leak between reservoir 1 and reservoir 2. All water meters were read for members residing within these boundaries. No leak was detected and the high flow from reservoir 2 subsided.

Maintenance

No maintenance this month

Actions needed by CBPOA

The water plant building is in dire need of paint. I would recommend that the building be painted this year. I can get bids if directed by the BOD to do so.