

Eastlake Water Services
16720 S. Carlin Bay Rd
Harrison, ID 83833

Carlin Bay Property Owners
Water Report for October-December 2012

Operations

The last report was for the month of September 2012. It is now December 2012 and I apologize for the delay in reporting for the months of Oct. and Nov.

Plant operations have been within DEQ specifications for the months of October and November, there were no violations. All required water tests for the year 2012 have been completed with the exception of our last 2-4D test for the last quarter of this year. No violations of all tests that have been done.

Maintenance

Since the September report we had another lightning storm that claimed another pair of lines in our communication cable. Out of a 12 pair cable we were down to one pair. Communication between reservoir 2 and reservoir 1 requires 3 pair. One pair for level sensor and 2 pair for the high and low level water alarm floats. The Board was notified and approved replacing the cable with another 12 pair cable. This was completed December 12th and we are can now fully communicate with reservoir 2.

The water plant was in dire need of staining. The Board approved and it was stained by J.L. Painting mid September.

The floor of the water plant requires sealing. A bid was requested from J.L. Painting to wash and epoxy, labor cost is \$700. Board approval is required. In addition within the same bid an estimate was requested to color code all the filtration water pipes per DEQ standards. Bid was \$700 for labor. Board approval required.

Actions needed by CBPOA

As noted above Board approval is required for floor epoxy and pipe color coding.