

Eastlake Water Services
16720 S. Carlin Bay Rd
Harrison, ID 83833

Carlin Bay Property Owners
Water Report for September 2013

Operations

Plant operations have been within DEQ specifications for the months of September there were no violations.

Nitrate and IOC Sodium tests have been submitted to Accurate Testing Labs. All tests required by DEQ other than the monthly Coli form have been completed for the year.

Maintenance

Air gap drain behind water plant, drains to pump to waste pond, is still leaking. R.C. Worst will be contacted for repair. They were out previously and tried to repair leak with liquid nails which did not work. The bell pipe, short 2 foot section of pipe, should be replaced.

Actions needed by CBPOA

None.